




Getting smart and circular

Janez Križan, A1 Slovenija
Director of New Business Development and Innovation





A large, dense pile of discarded smartphones, mostly black and silver, with some colorful cases visible. The phones are scattered across the entire frame, creating a textured background.

400.000 smartphones

Predictive maintenance








Trenutna aktivnost svetilke


On Off Brez povezave
Napake




Trenutna skupna poraba energije




Profil za zatemnitev



Dnevna poraba energije v zadnjih 30 dneh



Mesečna poraba energije v zadnjih 6 mesecih



Napredno Zemljevid

ADVANCED



MAP



Trenutni nivo napolnjenosti

	Ime	Naslov	Nivo napolnjenosti	Nazadnje osveženo	Aktiven
▶	WASTE_3042	Kozlovčeva Ulica / Via Kristjan Kozlovč 1, 6000 Koper, Slovenia	41.0%	2019-06-20 13:14:48	
▶	WASTE_3047	VENA PILONA KRALJEVA	8.0%	2019-06-20 11:51:29	
▶	WASTE_3041	CESTA NA MARKOVEC	35.0%	2019-06-20 10:09:38	
▶	WASTE_3045	Piranska Cesta / Via Pirano 1, 6000 Koper, Slovenia	9.0%	2019-06-20 08:09:18	
▶	WASTE_3043	, Koper, Slovenia	44.0%	2019-06-20 06:32:18	
▶	WASTE_3039	Vergerjev Trg / Piazzale Pier Paolo Vergerio 2, 6000 Koper, Slovenia	80.0%	2019-06-20 05:42:52	
▶	WASTE_3048	Dolinska Cesta / Strada Della Valle 381, 6000 Koper, Slovenia	42.0%	2019-06-19 15:59:18	
▶	WASTE_3040	Pristaniška ulica 41, Koper, Slovenia	100.0%	2019-04-22 08:55:45	
▶	WASTE_3044	Ulica Vena Pilon / Via Veno Pilon 4, 6000 Koper, Slovenia	53.0%	2019-04-22 00:55:42	
▶	WASTE_3046	TRG BROLO	100.0%	2019-03-18 03:40:29	

Prejšnja

Stran

1




od 1

10 vrstice

Naslednji


Število (ne)aktivnih

■ Neaktiven ■ Aktiven




Skupno število zabojnikov

■ <50% ■ >50% ■ >85%



Nivo napolnjenosti (%) v prejšnjem tednu

■ Embalaza



Dnevni nivo napolnjenosti v prejšnjem tednu

■ (%)



Zemljevid

MAP




AVTOMOBILI
27.2 %


TOVORNJAKI
31.8 %



KOLESA
40.9 %

A1 powered by **NOKIA**

Skupna odkrita vozila




Stanje prometa v zadnji uri



Stanje prometa glede na tip vozila

2019-06-13 - 2019-06-20



A1

Thank you



Senzorja kakovosti zraka
SmartSense_#01
AQI: 37



SO₂
0
[ug/m³]



O₃
73.3
[ug/m³]



Barometer
101.1
[kPa]



NO₂
74.6
[ug/m³]



PM₁
5.9
[ug/m³]



Vlažnost
54.6
[%]



CO
181.3
[ug/m³]



PM_{2.5}
7
[ug/m³]



Temperatura
32.9
[°C]




NO
2.3
[ug/m³]



PM
8.8
[ug/m³]



Dnevno povprečje IKZ v prejšnjem tednu



Dnevne najmanjše/povprečne/največje koncentracije

